



## Greater Bristol Bus Network (GBBN) Stage 3 Road Safety Audit, Exception Report

### Addendum Report for:

Whiteladies Road GBBN (changes made as of October 2012)

- 2.2.1 Signing installation complete, enforcement underway
- 2.3.2 All trip hazards at crossing points have been amended through snagging
- 2.3.3 Locations with standing water have been identified, amendment works to be ordered through the relevant contractor
- 3.1.1 All lining works and signing installation complete
- 3.1.2 All lining and HFS works complete
- 3.1.3 All lining works complete
- 3.1.5 All lining and HFS works complete; amended signage works to be ordered through the relevant contractor
- 3.1.6 This matter is out of the scope of GBBN as these tactiles were not amended as part of the project
- 3.1.9 All lining works and signing installation complete
- 3.1.10 The utility under the cover was so close to the surface that there was no depth available to install an inset cover
- 3.1.14 The new cover was installed by a utility company after the GBBN works, amendment will be pursued by the NRSWA team; the post has been removed; signing installation complete
- 3.1.16 Signing installation complete
- 3.1.17 All lining works complete
- 3.1.19 Half end panel installed